

## St Benedict's School Walking Route Actions

### Actions

1. Visibility to the right at the junction of Thornside Road/ Thorn Brae is poor. It is recommended a footway extension on the South side of the junction is installed to improve visibility to the right. Traffic Section of the Department for action.
2. The North footway on High Street from MacDowall Street to Morrisons entrance is not complete. Maintenance Section of the Department for action.
3. The footway on the eastern side of Barrochan Road between Deafhillock Roundabout and Barrochan Interchange narrows due to overgrown vegetation and silt build up on footway. It is recommended the silt is removed on the footway and vegetation is cut back. Maintenance Section of the Department for action.
4. The South footway on Bridge of Weir Road, Linwood has overgrown vegetation. Instruction has been sent to the Maintenance Section of the Department for action.
5. The South footway on Bridge of Weir Road, Linwood there are two road sign poles partially obstruct the footway. It is recommended the two poles are relocated so they do not cause an obstruction. Traffic Section of the Department for action.
6. The visibility at the footpath link from Broom Terrace/Ash Place to Beith Road is obscured at Broom Terrace due to overgrown vegetation. It is recommended the vegetation is cut back at this location. Maintenance Section of the Department for action.
7. The visibility at Campbell Street/Canal Road junction is obscured by overgrown vegetation. . It is recommended the vegetation is cut back at this location. Maintenance Section of the Department for action.
8. Crossing from the footway at Campbell Street/Mavisbank Terrace to the West side of Campbell Street the width of carriageway is approx 9m wide. . It is recommended the carriageway width is reduced to reduce the crossing distance. Traffic Section of the Department for action.
9. The North footway on High Street from MacDowall Street to Morrisons entrance is not complete. Maintenance Section of the Department for action.
10. The footway on the eastern side of Barrochan Road between Deafhillock Roundabout and Barrochan Interchange narrows due to overgrown vegetation and silt build up on footway. It is recommended the silt is removed on the footway and vegetation is cut back. Maintenance Section of the Department for action.
11. The South footway on Bridge of Weir Road, Linwood has overgrown vegetation. Instruction has been sent to the Maintenance Section of the Department for action.
12. The South footway on Bridge of Weir Road, Linwood there are two road sign poles partially obstruct the footway. It is recommended the two poles are relocated so they do not cause an obstruction. Traffic Section of the Department for action.
13. The North footway on High Street from MacDowall Street to Morrisons entrance is not complete. Maintenance Section of the Department for action.

## **St Benedict's School Walking Route Actions**

14. The footway on the eastern side of Barrochan Road between Deafhillock Roandabout and Barrochan Interchange narrows due to overgrown vegetation and silt build up on footway. It is recommended the silt is removed on the footway and vegetation is cut back. Maintenance Section of the Department for action.
15. The South footway on Bridge of Weir Road, Linwood has overgrown vegetation. Instruction has been sent to the Maintenance Section of the Department for action.
16. The South footway on Bridge of Weir Road, Linwood there are two road sign poles partially obstruct the footway. It is recommended the two poles are relocated so they do not cause an obstruction. Traffic Section of the Department for action.