

## **Paisley Grammar Walking Route Actions**

### **Actions**

1. Vegetation at the north-western property line of 158 Hawkhead Road is overgrown and narrows the effective width of the footway significantly. It is recommended that the vegetation is cut back to the property boundary to maintain a satisfactory footway width. This issue has been passed to the Maintenance Section of the Department for action.
2. Vegetation on the northern corner between Jennyswell Road and Hawkhead Road is overgrown. As a result the visibility of oncoming traffic on Jennyswell Road for pedestrians crossing from north to south is significantly reduced. It is recommended that the vegetation is cut back to the property boundary to maintain a satisfactory footway width. This issue has been passed to the Maintenance Section of the Department for action.
3. The push button on the signal controlled pedestrian crossing on Hurlet Road could not be depressed and as a result it would not stop traffic. The button was on the control panel located on the central island for pedestrians crossing the northbound carriageway of Hurlet Road. This fault was passed to the Traffic section for action.
4. Vegetation at on the western side of Hurlet Road between property line northern and southern property lines of Dykebarhill Farm overgrown and narrows the effective width of the footway significantly. It is recommended that the vegetation is cut back to the property boundary to maintain a satisfactory footway width. This issue has been passed to the Maintenance Section of the Department for action.
5. Visibility to the right is obscured by overhanging vegetation at Grahamston Crescent on Grahamston Road. Instruction has been sent to the Maintenance Section of the Department for action.
6. The footway at the end of Grahamston Crescent needs vegetation cleared. Instruction has been sent to the Maintenance Section of the Department for action.