

Gryffe High School Walking Route Actions

Actions

1. The route provided by the Councils Education & Leisure Services indicated crossing the western arm of the Clevans Road/Donaldfield Road junction. However there is virtually no footway provision on the northern side of this crossing point due to the overgrown bushes. This issue has been passed to the Maintenance Section of the Department for action.
2. Vegetation along the northern side of Clevans Road should be cut back to the property boundaries to ensure the effective footway width is maximised. The footway is poorly surfaced with a number of potential trip hazards. Some parts of this footway are adopted and other areas are not. The issue has been passed to the Maintenance Section of the Department for action.
3. On Main Road outside the Gibb Stuart property a post holding up an Elderly Persons warning sign is damaged and bent. This issue has been passed to the Traffic Section of the Department for action.
4. Lighting column R34 along Houston Road was damaged and should be repaired. This issue has been passed to the Councils Lighting Maintenance department.
5. Overgrown vegetation along Lawmarnock Road reduces visibility and available road space for pedestrians to walk and should be cut back to the property boundary. This issue has been passed to the Maintenance Section of the Department for action.
6. The footway along the eastern side of Ranfurly Place is in a poor state of repair with a number of trip hazards and narrows at points. In many locations kerbstones are at a greater level than the footway. Also access gates to the Aincroft property open out towards the road and on the date of inspection blocked the entire footway. These issues have been passed to the Maintenance Section of the Department for action.
7. Vegetation on the north side of Prieston Road between Ranfurly Place and Horsewood Road is overgrown and reduces the effective width. This issue has been passed to the Maintenance Section of the Department for action.
8. The footways along Hazelwood Road (north of Kilgraston Road) are in a poor state of repair with a number of trip hazards and narrows at points. The western/northern footway is generally in better condition than the eastern/southern. This footway is unadopted and the issue has been passed to the Maintenance Section of the Department for action.
9. A post which is holding a walking route directional sign located northwest of Lintwhite Crescent is damaged and should be replaced. This issue has been passed to the Traffic Section of the Department for action.
10. The stairway leading to the underpass at Houston Road has uneven surfaces possibly presenting a tripping hazard. This issue has been passed to the Maintenance section of the Departments for action.