

## St Andrew's Academy Walking Route Actions

### Actions

1. Vegetation at the north-western property line of 158 Hawkhead Road is overgrown and narrows the effective width of the footway significantly. It is recommended that the vegetation is cut back to the property boundary to maintain a satisfactory footway width. This issue has been passed to the Maintenance Section of the Department for action.
2. There is no clear sight-line North at the path on the East-side of Mossneuk Drive. **It** is recommended pupils cross Mossneuk Drive at Craigiebar Drive to the North side. The footway should be extended on Mossneuk Drive on the North side to the remote footpath. This issue has been passed to the Traffic Section of the Department for action.
3. Damaged footway and various trip hazards from the Corner of Neilston Road / Falside Road to 13 Falside Road (Southside). This footway is un-adopted and the issue has been passed to the Maintenance Section of the Department for action.
4. **At** the Junction of Neilston Road / Falside Road there were a number of faults; Dark Red (North bound) and Dark Amber (South bound), Central Island. These issues have been passed to the Traffic Section of the Department for action.
5. There is no lighting at the Underpass between Ferguslie Park Avenue and Millarston Drive; this could present trip hazards during darker months. This issue has been passed to the Lighting Section of the Department for action.
6. Damaged footway and various trip hazards from 2 to 36 Gordon Street (Southside), This footway is un-adopted and the issue has been passed to the Maintenance Section of the Department for action.
7. There is Narrow and damaged footway on the West of Caplethill Road, Southside of the junction at Caplethill Road / Glenburn Road. This issue has been passed to the Maintenance Section of the Department for action.
8. Traffic Signal Lights at the Junction of Neilston Road / Falside Road; Dark Red (North Bound) and Dark Amber (South Bound), Central Island. This issue has been passed to the Traffic Section of the Department for action.
9. There is a lack of footway for crossing on the south-side of the Greenock Road / Goudie Street Junction. It is recommended that the existing white line hatching be refurbished. This issue has been passed to the Traffic Section of the Department for action.
10. Damaged footway and various trip hazards outside 33 Springbank Road (Southside). This footway is un-adopted and the issue has been passed to the Maintenance Section of the Department for action.
11. Parked cars on the south-side of the Osprey House side Street at Inchinnan Road are causing a Crossing Point obstruction. **It** is recommended that the existing Give-way markings be refurbished with white line hatching on the north and south sides of the junction. This issue has been passed to the Traffic Section of the Department for action.
12. Parked cars on the south-side of the Falcon House side Street at Inchinnan Road are causing a Crossing Point obstruction. **It** is recommended that the existing Give-way

## **St Andrew's Academy Walking Route Actions**

markings be refurbished, with white line hatching on the north and south sides **of** the junction. This issue has been passed to the Traffic Section of the Department for action.

13. Damaged footway and various trip hazards from 104 - 106 New Sneddon Street (Eastside). This footway is adopted and the issue has been passed to the Maintenance Section of the Department for action.
14. Underdeveloped footway (No Wearing Course) from 86 - 98 New Sneddon Street (Eastside). This footway is adopted and the issue has been passed to the Maintenance Section of the Department for action.
15. The walking route on the West footway Gleniffer Road crosses Moredun Road that is a busy junction with a lack of footway at the northern corner. There are also other areas of missing footway on the West side between Corsebar Drive and Park Road. It is recommended pupils cross Gleniffer Road to the east footway at the pelican crossing near Moredun Road. The push buttons on the Pelican crossing were not working this was reported to the traffic section.
16. The hill at Park Road/Calside was covered in snow and ice at the time of the assessment, great care was taken on this section. It is recommended pedestrian barrier on the East side of the hill is installed to assist pupils walking the route. Passed to the Traffic section for action.
17. The pelican crossing at Neilston Road/Great Hamilton Street has damaged pedestrian guardrail on the central island. This was passed to the maintenance section for action.
18. Footway on West side of 124 Corsebar Road has various trip hazards. Passed to our Maintenance section for action.
19. On the West footway near 33 Stanley Road there are trip hazards. Passed to our Maintenance section for action.
20. On the West footway near 54 to 56 Stanley Road there are trip hazards. Passed to our Maintenance section for action.