

Gleniffer High School Walking Route Actions

Actions

1. **The** northern footway along Foxbar Road, between Gleniffer Road and Stravaig Walk, is narrowed by overgrown vegetation, this should be cut back to maximise the full footway width. This issue has been passed to the Maintenance Section of the Department for action.