

## Rashielea Primary School Walking Route Actions

### Actions

1. The Shell petrol station access/egress, 11m wide, this is very wide for pedestrians to cross. Pedestrians have to look for vehicles on the circulatory and joining the roundabout as well as vehicles taking egress from the petrol station. This is exacerbated when pedestrians are on the East side of the junction as they have to look over their shoulder to look for gaps. It is recommended a traffic island is constructed at the access to cross the road in 2 stages. Passed to Traffic Section of the Department for action.
2. The Pelican crossing on A726 Bridgewater was vandalised, the green aspect was missing. This was reported to the Traffic section of the Department for action.
3. Mainhill at the Zebra crossing an area of footway requires reinstating. Passed to Maintenance Section of the Department for action.
4. The remote footpath behind 18 Mainhill Gardens has a damaged Street light at R6. Passed to Street Lighting Section of the Department for action.
5. Mainhill has recently been resurfaced but the road markings have not been replaced. Passed to Traffic Section of the Department for action.
6. Pedestrians from 143 to 193 Mainhill require to cross Mainhill to join the North footway. Crossing from the North to the South side visibility to the right is restricted by overgrown vegetation. Maintenance Section of the Department for action.
7. From the footbridge over the A726 to the Bridgewater Shopping Centre there are steps or a ramp coming away from the footbridge. The landing areas at the top of the steps have subsided and are a potential trip hazard. Passed to Maintenance Section for action.
8. The remote footpath behind 24 Mainhill Gardens has a damaged Street light at R6. Passed to Street Lighting Section for action.
9. Mainhill has recently been resurfaced but the road markings have not been replaced. Passed to Traffic Section of the Department for action.
10. Pedestrians from 143 to 193 Mainhill require to cross Mainhill to join the North footway. Crossing from the North to the South side visibility to the right is restricted by overgrown vegetation. Passed to the Maintenance Section of the Department for action.
11. Crossing from the Sports Centre, South across the raised table, visibility to the left is restricted by overgrown vegetation. Passed to Maintenance Section for action.
12. The Zebra crossing at Kilpatrick Drive has been upgraded to an official crossing. An assessment will be carried out to see if it meets the criteria for a School Crossing Patroller. Passed to Traffic Section for action.
13. The crossing point at Newshot Drive near 70 Mains River has also been altered, with a central island to assist pedestrians. An assessment will be carried out to see if it meets the criteria for a School Crossing Patroller. Following discussions it was agreed to upgrade to a Pelican crossing at this location. Passed to Traffic Section for action.